

## **BRIDGE ANALYSIS AND RATINGS**

 BRIDGE NO.:
 270018

 COUNTY:
 DARE

 STATE PROJECT NO.:
 WBS 42080.1.80

 ANALYSIS DATE:
 3/17/2022



FINAL REVIEW BY: Mindy Isenhour, PE FINAL REVIEW DATE: 3/17/2022

	NORTH CAROLINA DEPARTMENT OF TRANSPORTATION							
STRUCTURES MANAGEMENT UNIT - ANALYSIS SECTION								
RATING SUMMARY SHEET								
BRIDGE NUMBER: 270018 COMPLIED B							DATE:	3/17/2022
							3/17/2022	
Non-Interstate Highway Bridge								
			Prestressed					
			Concrete					
	Member	Truck Weight	Cored Slab					
	Span Length		41 ft.					
	Beam Spacing		3 ft.					
	(C=Continuous)	. = -						
	Analysis Method	LFR						
HS Invento	·	36.00	16.60					
HS Operati		36.00	27.70					
⊆	SNSH	13.50						
Ru	SNGARBS2	20.00						
<u><del>0</del></u>	SNAGRIS2	22.00						
hic	SNCOTTS3	27.25						
<b>^</b>	SNAGGRS4	34.93						
<u>e</u>	SNS5A	35.55						
Single Vehicle Run	SNS6A	39.95						
S	SNS7B	42.00						
	TNAGRIT3	33.00						
	TNT4A	33.08						
un n	TNAGRIT4	43.00						
TTST Run	TNAGT5A	45.00						
ST	TNAGT5B	45.00						
	TNT6A	41.60						
	TNT7A	42.00						
	TNT7B	42.00						_
CALCULATED POSTING: DESIGN LOADING:								
No Posting Required HS-20								
CONTROLL	ING MEMBER:				INVENTOR	V DATING:		
CONTROLL	IING IVIEIVIDEN.				INVENTOR		16.6	
						110	10.0	
EXISTING P	OSTING:				OPERATING	G RATING:		
Not Poste					OPERATING RATING:  HS 27.7			
11011 0010	ч							
RECOMEN	NDED POSTING:				ITEM 70 -	BRIDGE PO	STING	
No Postin	g Required				CODE:	5		
ANALYSIS INVENTORY RATING : <b>EJ</b> OPERATING RATING <b>EJ</b>					EJ			
METHOD: Engineering Judgement								
POSTING RATING: EJ								
OVERLOAD BRIDGE ONLY: No HS OPERATING DROPPED 3 TONS OR MORE: No								
COMMENTS: Assigned rating was used due to missing plans								



801 Jones Franklin Rd. Raleigh, NC 27606-3394

Bridge Number:	270018
County:	Dare
Inspection Date:	2/17/2022
Inspected by:	BJE, JEH

Rating by: BJE
Date: 3/17/2022
Checked by: MBI
Date: 3/17/2022

# **ASSIGNED LOAD RATING**

### **DESIGN PLANS**

No plans were provided by NCDOT at notice to proceed. NCDOT and Town of Southern Shores officials were contacted but plans for this site were not found.

### **ASSUMPTIONS**

Bridge does not match any standard set of plans. Therefore, a rating has been assigned based on the condition of the structure at the time of inspection.

Load ratings assigned based on assigned rating methodology as described by NCDOT memos.

#### **STRUCTURE INFORMATION**

Туре	Precast Prestressed Concrete Cored Slab
Date of Inspection	2/17/2022
Spans/Barrels	2
Span Lengths	36'-0" 41'-0"
Beam Size/Spacing	36"x18" @ 3'-0"
Skew	0°
<b>Continuous for Live</b>	
Load	No
# of Beams	11
Width of Bridge/Length	
of Culvert	33'-0" Out-to-Out
Year of Construction	1990



801 Jones Franklin Rd. Raleigh, NC 27606-3394 Bridge Number: 270018

County: Dare
Inspection Date: 2/17/2022
Inspected by: BJE, JEH

Rating by: BJE
Date: 3/17/2022
Checked by: MBI
Date: 3/17/2022

# **ASSIGNED LOAD RATING**

#### **SUMMARY OF FIELD EVALUATION**

## **Condition Ratings**

#### **National Bridge Inventory Items**

Tradicinal Pringe inventory items				
ltem	Grade Scale	Grade		
Item 58: Deck	0-9, N	7		
Item 59: Superstructure	0-9, N	7		
Item 60: Substructure	0-9, N	6		
Item 61: Channel and Channel Protection	0-9, N	7		
Item 62: Culvert	0-9, N	N		
Item 71: Waterway Adequacy	0-9, N	7		
Item 72: Approach Roadway Alignment	0-9, N	8		

#### **Comments on Structural Defects**

Cracking throughout asphalt wearing surface. Exterior girders appear to be pushing/rotating away from adjacent girders with some efflorescence buildup. Cracking and spalling found throughout Bent 1 cap. See inspection report for details.

### **ASSIGNED RATING**

Rating for: Prestressed Concrete

Design Loading: HS20
HS Inventory Rating: HS16.6
HS Operating Rating: HS27.7

Project Engineers Page 6 April 1, 2016

- Condition of load carrying components.
- Level of load path redundancy.
- Reconstruction or modifications to the structure.
- Measurable deformations.
- Comparison to comparable structures of known design.
- Observed performance of the structure under traffic.

#### Prestressed Concrete Bridges

Review inspection reports for evidence of structural distress, such as flexural or shear cracks. For prestressed concrete bridges use the lower of the superstructure or substructure condition ratings (NBI Items #59 and #60) and Table 3 to assign a load rating. Consider whether the condition rating reflects the load carrying capacity of the structure. If a low condition rating is due to a deficiency that does not affect the structure's load carrying capacity, a higher engineering judgement rating is appropriate, if adequate justification is furnished.

Table 3: Prestressed Concrete Bridges - Engineering Judgement Load Rating

Lowest NBI Condition Rating (Superstructure and Substructure only)	Inventory Rating (RF <sub>Inv.</sub> )	Operating Rating (RF <sub>Op.</sub> )		
9	HS20.0 (1.00)	HS33.4 (1.67)		
8	HS20.0 (1.00)	HS33.4 (1.67)		
7	HS19.0 (0.95)	HS31.7 (1.59)		
6	HS16.6 (0.83)	HS27.7 (1.39)		
5	HS12.6 (0.63)	HS21.0 (1.05)		
4	HS8.0 (0.40)	HS13.4 (0.67)		
3 or 2	• Assign appropriate rating less than that for NBI Condition Rating of 4.			
0 or 1	Bridge closed.			

Substructure grade of 6 dictates rating.

For structures with a superstructure condition rating < 5, use engineering judgement to also estimate a safe load carrying capacity, for single vehicles (SV) with 2 to 7 axles and truck tractor semi-trailers (TTST) with 3 to 7 axles. Structures with a NBI superstructure condition rating  $\leq$  3 and are open to traffic will require extensive justification for the engineering judgement load rating. Justification should include, but is not limited to an assessment of the following:

- Condition of load carrying components.
- Level of load path redundancy.
- Reconstruction or modifications to the structure.
- Measurable deformations.
- Comparison to comparable structures of known design.
- Observed performance of the structure under traffic.